SAINT LOUIS COUNTY DEPARTMENT OF TRANSPORTATION

BID TABULATION

PROJECT: 2017 WEST COUNTY ITS SEGMENTS ST. LOUIS COUNTY PROJECT NO.: AR-1644 FEDERAL PROJECT NO.: CMAQ-4900(632) DATE OF BIDS RECEIVED: 7/18/2018

| | | | TGB, Inc. | | | Meyer Electric Company, Inc. | | Gerstner Electric Inc. | |
|------------------------|-----------------------------------------------------------------------------------------|-------|-------------------------|------------------------|------------------------|------------------------------|------------------|---------------------------------------|------------------------|
| | | | Core Bid - Bid Option 1 | | | Core Bid - Bid Option 1 | | Core Bid - Bid Option 1 | |
| Item Numbe | Pr Description | Unit | Quantity | Unit Price C | alculated Total | Unit Price | Calculated Total | Unit Price | Calculated Total |
| ROADWAY I | TEMS | | | | | | | | |
| 612-30.10 | Standard Traffic Control Devices | L.S. | 1 | . , | \$6,000.00 | \$5,000.00 | | | \$9,940.00 |
| 619-00.00 | Mobilization | L.S. | 1 | \$48,000.00 | \$48,000.00 | \$44,000.00 | \$44,000.00 | \$30,500.00 | \$30,500.00 |
| 806-00.00 | Erosion Control Measures (Sites less than 1 acre) | L.S. | 1 | \$50.00 | \$50.00 | \$5,000.00 | \$5,000.00 | \$100.00 | \$100.00 |
| 806-45.00 | Inlet Protection | L.S. | 1 | \$50.00 | \$50.00 | \$1,500.00 | | | \$100.00 |
| | OADWAY ITEMS | | | , | \$54,100.00 | , , | \$55,500.00 | ļ. | \$40,640.00 |
| COUNTY TRA | AFFIC SIGNAL ITEMS | | | | | | | | |
| | | | | | | | | | |
| 1 | Controller, Fully Actuated, (8 Phase Timer, in | | | | | | | | |
| | Aluminum Cabinet Approx. 55"H x 44"W x 26"D, | | | | | | | | |
| | Wired for 8 Phase Operation) w/Internal Fiber Optic Modem and Termination Housing, TS2, | | | | | | | | |
| 904-43.88 | Type 2, w/Battery Backup | Each | 13 | \$19,900.00 | \$258,700.00 | \$23,354.00 | \$303,602.00 | \$28,624.00 | \$372,112.00 *(1) |
| 301 10100 | Fiber Optic Cable Termination Housing, in | | 10 | \$13 ,300.00 | ¥230), 00.00 | ψ25,55 H.00 | , | ψ20)02 1100 | ψο/2/212.00 (1) |
| | Aluminum Cabinet Approx. 36"H x 24"W x 22"D, | | | | | | | | |
| 904-46.30 | Ground Mounted | Each | 5 | \$4,650.00 | \$23,250.00 | \$5,429.00 | \$27,145.00 | \$4,482.00 | \$22,410.00 |
| | Detector, Vehicle Induction Loop, Card Rack Mtg., | | | | | | | | |
| | 2 Channel, w/Delay and Extension Timing and | | | | | | | | |
| 904-49.35 | Relay Outputs | Each | 63 | \$160.00 | \$10,080.00 | | | | \$12,285.00 |
| 904-52.00 | Conduit, 2" | L.F. | 15678 | \$7.50 | \$117,585.00 | \$10.00 | | · · · · · · · · · · · · · · · · · · · | \$159,915.60 |
| 904-52.02 904-54.00 | Conduit, 2" on Bridge Structure Conduit, 4" | L.F. | 138 | \$32.00 \$18.00 | \$4,416.00 \$792.00 | \$35.00 \$12.00 | | | \$2,622.00 \$671.00 |
| 904-54.00 | Conduit, 4 | L.F. | 44 | \$18.00 | \$792.00 | \$12.00 | \$526.00 | \$15.25 | \$0/1.00 |
| | Conduit Repair (locate broken conduit, excavate, | | | | | | | | |
| | remove existing cable, repair/replace conduit, | | | | | | | | |
| | reinstall cable, backfill and restore) (Does not | | | | | | | | |
| | include sidewalk or pavement removal and | | | | | | | | |
| 904-74.99 | replacement) | Each | 1 | \$750.00 | \$750.00 | \$400.00 | \$400.00 | \$995.00 | \$995.00 |
| 904-82.06 | Cable, Power, #6 Gauge, 1 Conductor | L.F. | 840 | \$1.60 | \$1,344.00 | \$1.10 | \$924.00 | \$1.50 | \$1,260.00 |
| 904-84.00 | Wire, Stranded Ground, #6 Gauge | L.F. | 420 | \$1.60 | \$672.00 | \$1.10 | \$462.00 | \$1.40 | \$588.00 |
| | Cable, Communication, Fiber Optic, 36 Fibers (30 | | | | | | | | |
| 904-85.36 | Single-Mode and 6 Multi-Mode) | L.F. | 22710 | \$3.00 | \$68,130.00 | \$3.12 | \$70,855.20 | \$3.40 | \$77,214.00 |
| | Cable, Communication, Power, PTZ Camera, #24 | | | | | | | | |
| 904-85.81 | Gauge, 4 Pair (Shielded) | L.F. | 320 | \$2.00 | \$640.00 | \$1.50 | \$480.00 | \$1.75 | \$560.00 |
| 004 96 01 | Power Supply Assembly, on Wood Utility Pole, | Fach | , | ¢2 200 00 | ¢8 800 00 | ¢2,000,00 | ¢12,000,00 | ¢1 200 00 | ¢E E60 00 |
| 904-86.01 | 120/240 Volt Preformed Pull Box (17"W x 30"L x 26"min.H), | Each | 4 | \$2,200.00 | \$8,800.00 | \$3,000.00 | \$12,000.00 | \$1,390.00 | \$5,560.00 |
| 904-89.17 | Reinforced Polymer Concrete | Each | 57 | \$950.00 | \$54,150.00 | \$1,000.00 | \$57,000.00 | \$915.00 | \$52,155.00 |
| 304-83.17 | Preformed Pull Box (17"W x 30"L x 26"min.H), | Lacii | 37 | \$550.00 | \$54,150.00 | \$1,000.00 | 337,000.00 | 3313.00 | \$32,133.00 |
| | Reinforced Polymer Concrete w/1' Concrete | | | | | | | | |
| 904-90.17 | Apron | Each | 6 | \$1,100.00 | \$6,600.00 | \$1,200.00 | \$7,200.00 | \$1,125.00 | \$6,750.00 |
| 904-91.00 | Pad, Controller, Concrete | Each | 5 | | \$5,000.00 | | | | \$2,625.00 |
| 904-91.90 | Base, Type E-3, Concrete | Each | 5 | \$2,000.00 | \$10,000.00 | \$1,000.00 | \$5,000.00 | \$2,045.00 | \$10,225.00 |
| | | | | | | | | | · |
| 904-95.10 | Opening Drilled in Existing Concrete Pull Box | Each | 4 | \$350.00 | \$1,400.00 | | | | \$564.00 |
| 904-95.30 | Removal of Preformed Pull Box | Each | 14 | | \$2,520.00 | | | · · · · · · · · · · · · · · · · · · · | \$2,940.00 |
| 904-97.33 | Removal of Existing Controller Cabinet | Each | 13 | \$150.00 | \$1,950.00 | \$350.00 | \$4,550.00 | \$220.00 | \$2,860.00 |
| | School Zone Beacon Wireless Communication | | | | | | | | |
| 906-92.00 | Equipment (Installed by Others) | Each | 1 | \$5,400.00 | \$5,400.00 | \$6,000.00 | \$6,000.00 | \$5,650.00 | \$5,650.00 |
| | OUNTY TRAFFIC SIGNAL ITEMS | 20011 | 1 - | Ş3, 10 0.00 | \$582,179.00 | | \$683,260.20 | | \$739,961.60 *(2) |
| | | | | | ψ302,173.00 | | 7003,200.20 | | Ç7.33,301.00 (2) |
| PEDESTRIAN | Remove and Replace Concrete Sidewalk (4" | | 1 | T | | T | Т | <u> </u> | |
| 608-60.94 | Thick) | S.Y. | 319.2 | \$98.00 | \$31,281.60 | \$80.00 | \$25,536.00 | \$99.50 | \$31,760.40 |
| | EDESTRIAN AND BICYCLE ITEMS | J.1. | 313.2 | \$50.00 | \$31,281.60 | | \$25,536.00 | | \$31,760.40 |
| • | - | | | | , = ,==== | | ,, | | , : , ; : : : : : |
| PROJECT TO | TALS | | | | \$667,560.60 | | \$764,296.20 | | \$812,362.00 *(3) |
| | | | | | | | | | |

Corrected From: \$281,112.00 *(1) Corrected From: \$648,961.60 *(2) Corrected From: \$721,362.00 *(3)